

Work Order ID 85699

85699

Page 1

June-13-12 4:05:02 PM

Item ID: D3826-041

Accept

N900040100

Setup Start *NS1*

Revision ID:

Stop *NS2*

Item Name: Rib / Gusset Assembly

Start Date: 13/06/2012 Start Qty: 6.00

6
6

Cust Item ID:

Required Date: 27/06/2012 Req'd Qty: 6.00

Customer:

Reference:

Approvals: Process Plan: ML5

Date: 12/06/14

Tooling:

Date:

Run Start *NR1*

QC:

Date:

SPC (Y/N):

Date:

Stop *NR2*

Sequence ID/ Work Center ID	Operation Description	Set Up/ Run Hours	Tool ID	Tool #	Plan Code	Accept Qty	Reject Qty	Reject Number	Insp. Stamp
--------------------------------	--------------------------	----------------------	---------	--------	--------------	---------------	---------------	------------------	----------------

Draw Nbr

Revision Nbr

D3826

Rev B

100

0.00

1.00

Large Fab

Large Fab

Memo

0.00

Large Fab

1- assemble D2325 support gusset together
2- locate D2325 on rib and weld as per dwg D3826
A/R ER316 S.S. Rod Batch: M121602

1cc 12-7-24

110

QC9- Inspect visual per QSI004- Fusion Welds

0.00

1.10

QC

Memo

0.00

Quality Control

6 12-7-25

DAS
24
8-08

120

QC5- Inspect part completeness to step on W/O

0.00

1.20

QC

Memo

0.00

Quality Control

DAS
16
12/07/25

(+6)

6

W/O:		WORK ORDER CHANGES					
DATE	STEP	PROCEDURE CHANGE	By	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector

Part No: _____ PAR #: _____ Fault Category: _____ NCR: Yes No DQA: _____ Date: _____

Resolution: _____ Disposition: _____ QA: N/C Closed: _____ Date: _____

NCR:		WORK ORDER NON-CONFORMANCE (NCR)						
DATE	STEP	Description of NC Section A	Corrective Action Section B			Verification Section C	Approval Chief Eng	Approval QC Inspector
			Initial Chief Eng	Action Description Chief Eng	Sign & Date			

NOTE: Date & initial all entries

Work Order ID 85699

85699

Page 2

June-13-12 4:05:02 PM

Item ID: D3826-041

Accept

N900040100

Setup Start *NS1*

Revision ID:

Stop *NS2*

Item Name: Rib / Gusset Assembly

Start Date: 13/06/2012 Start Qty: 6.00

6

Cust Item ID:

Required Date: 27/06/2012 Req'd Qty: 6.00

6

Customer:

Reference:

Approvals: Process Plan: Date: Tooling: Date:

Run Start *NR1*

QC: Date: SPC (Y/N): Date:

Stop *NR2*

Sequence ID/ Work Center ID	Operation Description	Set Up/ Run Hours	Tool ID	Tool #	Plan Code	Accept Qty	Reject Qty	Reject Number	Insp. Stamp
--------------------------------	--------------------------	----------------------	---------	--------	--------------	---------------	---------------	------------------	----------------

130 Identify as per dwg & Stock Location: WA

0.00

130

Packaging Memo

0.00

Packaging

6x 12/07/25

140 QC21- Final Inspection - Work Order Release

0.00

140

QC Memo

0.00

Quality Control

12/7/31

MCJ 12/07/30

W/O:		WORK ORDER CHANGES					
DATE	STEP	PROCEDURE CHANGE	By	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector

Part No: _____ PAR #: _____ Fault Category: _____ NCR: Yes No DQA: _____ Date: _____

Resolution: _____ Disposition: _____ QA: N/C Closed: _____ Date: _____

NCR:		WORK ORDER NON-CONFORMANCE (NCR)						
DATE	STEP	Description of NC Section A	Corrective Action Section B			Verification Section C	Approval Chief Eng	Approval QC Inspector
			Initial Chief Eng	Action Description Chief Eng	Sign & Date			

NOTE: Date & initial all entries

Picklist Print

June-13-12 4:05:07 PM

Page 1

Work Order ID: 85699

85699

Parent Item: D3826-041

D3826-041

Parent Item Name: Rib / Gusset Assembly

Start Date: 13/06/2012

Required Date: 27/06/2012

Start Qty: 6.00

Required Qty: 6.00

Comments: IPP Rev:A 08-12-01 new issue DD verified by:EC

Component Item ID/ Item Name	Replacement Item ID	Mfg/ Purch	Bin Item	Primary Location	Last Location	Route Seq ID	Unit of Measure	Qty on Hand	Qty per Kit	Total Qty	Qty Issued	Date Issued	Status
D2235-1 *D2235-1* Basket Rib		Manufactured	No			100	Each	16.0000	1	6			
										**	CC 12-7-24		

Location	Loc Qty	Loc Code
WA	12	
78636	5	
81910	1	
82951	6	
WA005	4	
66895	4	

D3929-041 *D3929-041* Gusset Assembly		Manufactured	No			100	Each	5.0000	1	6			
										**	CC 12-7-24		

Location	Loc Qty	Loc Code
WA005	5	B86396
77675	2	
79152	2	
81255	1	

D3929-042 *D3929-042* Gusset Assembly		Manufactured	No			100	Each	7.0000	1	6			
										**	CC 12-7-24		

Location	Loc Qty	Loc Code
WA005	7	B86380
79154	7	

W/O:		WORK ORDER CHANGES					
DATE	STEP	PROCEDURE CHANGE	By	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector


Part No: _____ PAR #: _____ Fault Category: _____ NCR: Yes No DQA: _____ Date: _____

Resolution: _____ Disposition: _____ QA: N/C Closed: _____ Date: _____

NCR:		WORK ORDER NON-CONFORMANCE (NCR)						
DATE	STEP	Description of NC Section A	Corrective Action Section B			Verification Section C	Approval Chief Eng	Approval QC Inspector
			Initial Chief Eng	Action Description Chief Eng	Sign & Date			

NOTE: Date & initial all entries

ITEM	QTY. -041	P/N	DESCRIPTION
1	X	D3826-041	RIB/GUSSET ASSY
11	1	D2235-1	RIB
12	1	D3929-041	GUSSET ASSEMBLY
13	1	D3929-042	GUSSET ASSEMBLY



D3826-041 RIB/GUSSET ASSY

SHOP COPY
RETURN TO
ENGINEERING
UNCONTROLLED COPY
SUBJECT TO AMENDMENT
WITHOUT NOTICE
WORK ORDER

NO. 85699 MLJ

12/06/14

RELEASED
01/04/12

B	D3929-041/-042 WERE D2325 (ZN D3-1 & ZN D6-2); UPDATED WEIGHT (ZN A8-1). REASON: SEE NCR#09-042.	MB	09.04.16
A	NEW ISSUE	MB	08.09.23
REV.	DESCRIPTION	BY	DATE
DESIGN	16		
DRAWN	16		
CHECKED	16		
MFG. APPR.	16		
APPROVED	16		
DE APPR.	16		
DATE	09.04.16		

- NOTES:**
1) MATERIAL: N/A
2) FINISH: NONE
3) TOLERANCES: PER DART QSI 018 UNLESS OTHERWISE NOTED
4) UNITS: INCHES UNLESS OTHERWISE NOTED
5) BREAK SHARP EDGES: 0.005 TO 0.010 MAX
6) IDENTIFICATION: N/A
7) WEIGHT: 3.32 lbs

DART AEROSPACE LTD
HAWKESBURY, ONTARIO, CANADA
DRAWING NO. **D3826** REV. B
TITLE **RIB/GUSSET ASSY** SCALE NTS
SHEET 1 OF 2

COPYRIGHT © 2008 BY DART AEROSPACE LTD
THIS DOCUMENT IS PRIVATE AND CONFIDENTIAL AND IS SUPPLIED ON THE EXPRESS CONDITION THAT IT IS
NOT TO BE USED FOR ANY PURPOSE OR COPIED OR COMMUNICATED TO ANY OTHER PERSON WITHOUT
WRITTEN PERMISSION FROM DART AEROSPACE LTD

W/O:		WORK ORDER CHANGES					
DATE	STEP	PROCEDURE CHANGE	By	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector

Part No: _____ PAR #: _____ Fault Category: _____ NCR: Yes No DQA: _____ Date: _____

Resolution: _____ Disposition: _____ QA: N/C Closed: _____ Date: _____

NCR:		WORK ORDER NON-CONFORMANCE (NCR)						
DATE	STEP	Description of NC Section A	Corrective Action Section B			Verification Section C	Approval Chief Eng	Approval QC Inspector
			Initial Chief Eng	Action Description Chief Eng	Sign & Date			

NOTE: Date & initial all entries

B D3929-042
GUSSET ASSEMBLY

B D3929-041
GUSSET ASSEMBLY

TYP

0.250

D2235-1
RIB

D3826-041 RIB/GUSSET ASSY

RELEASED
9/04/12

DESIGN		DART AEROSPACE LTD	
DRAWN		HAWKESBURY, ONTARIO, CANADA	
CHECKED		DRAWING NO.	REV. B
MFG. APPR.		D3826	SHEET 2 OF 2
APPROVED		TITLE	SCALE
DE APPR.		RIB/GUSSET ASSY	NTS
DATE	09.04.16	<small>COPYRIGHT © 2008 BY DART AEROSPACE LTD THIS DOCUMENT IS PRIVATE AND CONFIDENTIAL AND IS SUPPLIED ON THE EXPRESS CONDITION THAT IT IS NOT TO BE USED FOR ANY PURPOSE OR COPIED OR COMMUNICATED TO ANY OTHER PERSON WITHOUT WRITTEN PERMISSION FROM DART AEROSPACE LTD.</small>	

DAS
24

24

24

W/O:		WORK ORDER CHANGES					
DATE	STEP	PROCEDURE CHANGE	By	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector

Part No: _____ PAR #: _____ Fault Category: _____ NCR: Yes No DQA: _____ Date: _____

Resolution: _____ Disposition: _____ QA: N/C Closed: _____ Date: _____

NCR:		WORK ORDER NON-CONFORMANCE (NCR)						
DATE	STEP	Description of NC Section A	Corrective Action Section B			Verification Section C	Approval Chief Eng	Approval QC Inspector
			Initial Chief Eng	Action Description Chief Eng	Sign & Date			

NOTE: Date & initial all entries